REPORT

14201

DATE

RECEIVED

CABLE:

LABORATORY NO.

FRANKLIN AVENUE

March 21, 1988

TRUELABS

24231

TUSTIN, CALIFORNIA 92680 AREA CODE 714 • 730-6239

AREA CODE 213 . 225-1564

April 8, 1988

TRUESDAIL LABORATORIES, INC.

HEMISTS - MICROBIOLOGISTS - ENGINEERS

DEVELOPMENT

Douglas Aircraft Company

Internal Mail Code 211-40 CLIENT 3855 Lakewood Blvd.

Long Beach, CA 90846

Attn: Robert M. Tomko

SAMPLE

INVESTIGATION

P.O.#T & M 23465 C

Storm drain inspection - monthly (March)

As requested by the CRWQCB for MPDES permit #'s CA0001406 & CA0001414

RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on March 21, 1988, at the Douglas, Torrance facility and Long Beach facility (003). The discharge was tested for flow rate, pH, and temperature. A grab sample was returned to the laboratory's and analyzed according to the American Public Health Association's "Standard Methods," 16th Edition. results are as follows:

Sample I.D.	Date	Time	Flow - gpd	Temp OF	pH Units
Long Beach	3/21/88	2:30	61,214	69	7.0
(003) Torrance	3/21/88	12:55	No discharge	72	7.0

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.

BOE-C6-0212306


TRUESDAIL LABORATORIES, INC.

-2-

Douglas Aircraft Company Laboratory No. 24231

Sample I.D.

Nitrate (353.3) Phosphorus (365.3) Sulfate (375.4) Iron (Fe, 236.1) Magnesium (Mg, 242.1) Zinc (Zn, 289.1)



Long Beach 003, mg/1

514 0.36 150 4.5 12 0.16

Respectfully submitted,

TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor